

From: dbofinger@kemron.com
Sent: 6/20/2012 1:19:49 PM
To: "Richard Fetzer/R3/USEPA/US@EPA" <Fetzer.Richard@epamail.epa.gov>
CC: "James Adams" <jadams@kemron.com>; "Joanna Mcdonald/R3/USEPA/US@EPA" <Mcdonald.Joanna@epamail.epa.gov>
Subject: RE: [Ex. 6 - Personal Privacy] rd update

Rich,

I called and left a voice mail on your phone. The generator is over at [Ex. 6 - Personal Privacy] Rd powering the Simmons trailer and is operating like it was intended. [Ex. 6 - Personal Privacy] was shown how to start and stop the generator so that the generator only runs when it is needed to provide electric to the pressure pump. Also the resident says that they hope to have power restored in the next few days. I respectfully ask that you have the work order revised to include the generator starting today and until the power is restored at [Ex. 6 - Personal Privacy] Rd.

Dave Bofinger
Response Manager
Kemron Environmental Services Inc
1359-A Ellsworth Industrial Blvd
Atlanta, GA 30318
e mail- dbofinger@Kemron.com
Cell phone- 404 725 3257
Phone-404 636 0928 Fax 404 636 7162
Visit us at www.kemron.com

From: Richard Fetzer [mailto:Fetzer.Richard@epamail.epa.gov]
Sent: Wednesday, June 20, 2012 9:15 AM
To: David Bofinger
Cc: James Adams
Subject: Re: [Ex. 6 - Personal Privacy] rd update

Fine with me.

Richard M. Fetzer
Federal On-Scene Coordinator
100 Gypsum Road
Stroudsburg, PA. 18360
(570) 402 7108

From: "David Bofinger" [dbofinger@kemron.com]
Sent: 06/20/2012 09:13 AM AST
To: Richard Fetzer
Cc: "James Adams" <jadams@kemron.com>
Subject: RE: [Ex. 6 - Personal Privacy] rd update

Rich,

After Paul gets here and can help we will take the generator out and have it supply power to the Simmons trailer. I believe that I told you that the resident said that she expected power again by Friday but I will inquire about this if I see a resident today. I also do not know which power company provides service to the property. I will contact you after 1pm if that works for you.

Dave Bofinger
Response Manager
Kemron Environmental Services Inc
1359-A Ellsworth Industrial Blvd
Atlanta, GA 30318
e mail- dbofinger@Kemron.com
Cell phone- 404 725 3257
Phone-404 636 0928 Fax 404 636 7162
Visit us at www.kemron.com

From: Richard Fetzer [<mailto:Fetzer.Richard@epamail.epa.gov>]
Sent: Wednesday, June 20, 2012 9:05 AM
To: David Bofinger
Cc: James Adams
Subject: Re: [Ex. 6 - Personal Privacy] update

Dave, my thought is that we temporarily supply a generator to power our rental tank system until the situation gets resolved. Is that still projected for tomorrow? I don't favor doing anything to the Cabot system. Let's talk later today. Do you know the electrical company the [Ex. 6 - Personal Privacy] are dealing with?

Richard M. Fetzer
Federal On-Scene Coordinator
100 Gypsum Road
Stroudsburg, PA. 18360
(570) 402 7108

From: "David Bofinger" [dbofinger@kemron.com]
Sent: 06/20/2012 08:45 AM AST
To: Richard Fetzer
Cc: <padams@kemron.com>
Subject: [Ex. 6 - Personal Privacy] rd update

Rich,

When I was out checking the water systems this morning I seen that the power is not on at [Ex. 6 - Personal Privacy] and they have the extension cords still running to the other mobile home. When I checked the Cabot tank it was down about 25 gallons from yesterday afternoon when Paul & I were over there so the Jet pump had been working.

However I did also notice that the jet pump for the Cabot supplied water system is also hot and

constantly running, when I tipped the enclosure so I could see the pump gage it was reading 20psi which I believe means that the pump is not functioning at this time, so I unplugged the pump from the extension cord supplying power from the other trailer. I am thinking that possibly the low electrical supply is causing this situation, when I go back out about 10am I will plug it back in and see if it works.

However if it does not, do you want us to supply power to the Simmons water trailer with a generator full time so it can function as it was designed to do? Or do you want to have a plumber look at the jet pump on the Cabot system and see why it is not functioning and possibly repair it? Or do nothing at all?

Let me know your thoughts.

Dave Bofinger
Response Manager
Kemron Environmental Services Inc
1359-A Ellsworth Industrial Blvd
Atlanta, GA 30318
e mail- dbofinger@Kemron.com
Cell phone- 404 725 3257
Phone-404 636 0928 Fax 404 636 7162
Visit us at www.kemron.com

Know Safety, No Accidents

P Before printing, think about ENVIRONMENTAL responsibility

The information contained in this email may be confidential and/or legally privileged. It has been sent for the sole use of the intended recipient(s). If the reader of this message is not an intended recipient, you are hereby notified that any unauthorized review, use, disclosure, dissemination, distribution, or copying of this communication, or any of its contents, is strictly prohibited. If you have received this communication in error, please reply to the sender and destroy all copies of the message. To contact us directly, send to postmaster@kemron.com. Thank you.

Know Safety, No Accidents

P Before printing, think about ENVIRONMENTAL responsibility

The information contained in this email may be confidential and/or legally privileged. It has been sent for the sole use of the intended recipient(s). If the reader of this message is not an intended recipient, you are hereby notified that any unauthorized review, use, disclosure, dissemination, distribution, or copying of this communication, or any of its contents, is strictly prohibited. If you have received this communication in error, please reply to the sender and destroy all copies of the message. To contact us directly, send to postmaster@kemron.com. Thank you.

Know Safety, No Accidents

P Before printing, think about ENVIRONMENTAL responsibility

The information contained in this email may be confidential and/or legally privileged. It has been sent for the sole use of the intended recipient(s). If the reader of this message is not an intended recipient, you are hereby notified that any unauthorized review, use, disclosure, dissemination, distribution, or copying of this communication, or any of its contents, is strictly prohibited. If you have

received this communication in error, please reply to the sender and destroy all copies of the message. To contact us directly, send to postmaster@kemron.com. Thank you.
